



PRE PURCHASE

INSPECTION REPORT



PRE PURCHASE INSPECTION REPORT

KIA

Car Description: CARNIVAL

Temp Gauge on arrival: Cold

Inspection date:

Inspection Location: NSW

Vin Number:

Registration:



This vehicle is eligible for [extended warranty](#)

Vehicle Specifics

Engine Number:

Cylinders: 4

Variant:

Fuel Type: DIESEL

Build date:

Transmission: 8 SP AUTOMATIC

Compliance Date:

Exterior Color: Black

Year Model:

Odometer:

Rego Expiry:

Repair Evidence: No

Body Type: 4D WAGON

Repairs Required: Yes

Drive Train: FWD



PRE PURCHASE INSPECTION REPORT

Body

Defects Noted

- Panels **Y**
- Doors / Locks **N**
- Glass / Mirrors **N**
- Seats / Belts **N**
- Body Repair Evidence **N**
- Interior Condition **N**
- Hail Damage Evidence **N**

Electrical

Defects Noted

- External Lights **Y**
- Battery **N**
- Wipers / Washers **N**
- Radio **N**
- Instrument Cluster **N**
- Heater / AC **N**
- Central Locking / Windows / Seats **N**

Underbody

Defects Noted

- Exhaust **N**
- Front/ Rear Suspension **N**
- Steering System **N**
- Wheels / Bearings **N**
- Transmission / Operation **N**
- Driveline / CV's / Universals **N**
- Brake System / Visual noninvasive **N**
- Tyre Wear / Spare tyre and jacks **Y**

Engine / Fluid Levels

Defects Noted

- Fuel **N**
- Cooling System / Fluid/ Levels **N**
- Brake System / Fluid / Levels **N**
- Steering System / Fluid / Levels **N**
- Oil System / Fluid / Levels **N**
- Ignition System **N**
- Airflow System **N**
- Mounts / Belts / Exhaust **N**

Road Test

Defects Noted

- Vehicle **N**
- Steering / Suspension **N**
- Noises **N**
- Drive Train **N**
- Temperature **N**
- Brake Operation **N**

Other

Defects Noted

- Vehicle **N**
- Steering / Suspension **N**
- Noises **N**
- Drive Train **N**



PRE PURCHASE INSPECTION REPORT

ECU Test Results

Vehicle information

Kia (Europe) CARNIVAL(KA4) 2023

License Plate:

VIN:

Mileage:

Diagnostics time:

Path: Auto scan>

Status report

| System Name | DIT Content | Status |
|--|-------------|--------|
| ENG (Engine) | 0 | Pass |
| A/T (Transaxle) | 0 | Pass |
| ABS/ESC (Anti Lock Brake/Electronic Stability Control) | 0 | Pass |
| ENG (Engine) | 1 | Fault |



PRE PURCHASE INSPECTION REPORT

| | | |
|--|---|-------|
| CLU (Cluster Module) | 0 | Pass |
| IBU-TPMS (Integrated Body Control Unit-Tire Pressure) | 0 | Pass |
| A/C (Air Conditioner) | 0 | Pass |
| CODE (Transmitter Code) | 0 | Pass |
| EPS (Motor Driven Power) | 1 | Fault |
| PSD (Power Sliding Door) | 0 | Pass |
| PTG (Power Tail Gate) | 0 | Pass |
| AVN (Audio Video Navigation) | 0 | Pass |
| IBU-BCM (Integrated Body Control Unit-Body Control Module) | 0 | Pass |
| ICU (Integrated Central) | 0 | Pass |
| IBU-SMK (Integrated Body) | 0 | Pass |
| F-CMR (Front View Camera) | 0 | Pass |
| FR (Front Radar) | 0 | Pass |



PRE PURCHASE INSPECTION REPORT

| | | |
|---|---|------|
| ADAS_P (Advanced Driver Assistance Systems Parking) | 0 | Pass |
| RCR (Rear Corner Radar) | 0 | Pass |
| DAU (Door Area Unit) | 0 | Pass |

2. AB (Airbag) — (1)

1.1. B136E:00 Rear passenger pretensioner resistance too high History

1. EPS (Motor Driven Power)

2.1. C1603:4B ECU Thermal protection History



PRE PURCHASE INSPECTION REPORT

Faults / Defects/ Test Drive/ Comments

- | | |
|----|-----------------------------|
| 1. | Tyre wear (20250320_083827) |
|----|-----------------------------|

Test Drive Comments: Carried out an inspection on Carnival. The body has light scratches, and the interior is in good condition. The passenger-side rear tyre has some edge wear. There are diagnostic codes in the system that need to be cleared by a workshop. In my opinion, this vehicle is in good and safe condition. All modifications must comply with NSW safety standards, and after modifications, the vehicle will need to be inspected and plated accordingly with a modification plate.



PRE PURCHASE INSPECTION REPORT

Defect Images





PRE PURCHASE INSPECTION REPORT

Mandatory Images





PRE PURCHASE INSPECTION REPORT

Mandatory Images





PRE PURCHASE INSPECTION REPORT

Mandatory Images





PRE PURCHASE INSPECTION REPORT

Mandatory Images





PRE PURCHASE INSPECTION REPORT

Mandatory Images





PRE PURCHASE INSPECTION REPORT

PPSR / History

Car History

From Equifax

Car History Dealer Report & PPSR Certificate Report generated on

| | |
|--------------------------|----------|
| VIN | |
| Make | KIA |
| Model | CARNIVA |
| Variant/series | |
| Body 4D WAGON | 4D WAGON |
| Transmission | |
| Year (first retail date) | |
| Color | BLACK |



*Picture provided is a sample only

QUICK SUMMARY



No stolen status reported



No written-off status reported



No financial interests reported



No odometer history reported



Vehicle registered



PRE PURCHASE INSPECTION REPORT

VEHICLE DETAILS

 Vehicle registered

VEHICLE REGISTRATION

| | |
|-------------------------|-----|
| Registration plate | |
| Registration state | NSW |
| Registration expiry Dat | |

FIRST SALE INFORMATION

| | |
|------------------------|---------|
| First sale date | |
| Postcode of first sale | |
| First | PRIVATE |

ENGINE DETAILS

| | |
|------------------|--------|
| Engine number | |
| Engine size | 2.2L |
| Cylinders/rotors | DT4 |
| Fuel type | DIESEL |
| Power (KW) | 148 |
| Torque (Nm) | 44 |

VEHICLE RATINGS


| | |
|----------------------|-------|
| ANCAP safety rating | ★★★★★ |
| Overall green rating | - |
| Air pollution rating | - |
| Greenhouse rating | - |



Car History notes:

Vehicle registration information is sourced via the PPSR. Refer to the PPSR Certificate below.

REPORTED ODOMETER HISTORY

 No odometer history reported

LAST REPORTED ODOMETER READING

| | |
|---------------|--|
| Kilometers | |
| Date reported | |

READING ENTERED BY YOU

| | |
|---------------|------------|
| Kilometers | |
| Date reported | 20/03/2025 |

The odometer history for this vehicle has been supplied to CarHistory by various sources within the automotive industry.

| Kilometers | Date reported | Alerts |
|------------|---------------|--------|
| | | |



PRE PURCHASE INSPECTION REPORT

Disclaimer

This is a visual, non-mechanical inspection only. Vehicle components will not be removed from during the inspection. You acknowledge that while the inspectors use accepted methods for faudetction, these methods may not identify all faults. The inspection includes the vehicles Body, Exterior, Electrical Systems, Engine systems, Cooling Systems, Exhaust Systems, Braking Sy Systems, Steering & Suspension Systems, Safety Systems, Transmission Systems, Final Drive Systems, Chassis, Understructure and a Road test, where possible.

The representative or company carrying out the inspection will not be responsible for defects before or after the inspection is carried out, items may not be visually identifiable at the time inspection.

The inspection is only current at the time and date of issue. It is not a roadworthy certificate an used as one. Inspectors are not required to follow up manufacturer recall notices. The inspecticverification against the vehicle condition at the time of inspection. It is buyer's responsibility to vehicle at the point of sale, we cannot make the decision for you or provide any advice.

The representative or company will not be responsible for the terms of any agreement, transact conversations between any persons in relation to any vehicle inspected. The representative or will not be responsible for resolving disputes between parties in relation to any transactor

Subject to all applicable laws, the representative or company does not provide any guarantee, warranty or representation regarding the nature, reliability, accuracy or completeness of any information contained in the inspection or the fitness of the information contained in the inspector any purpose intended.

The representative or company will not be liable to you for loss of use, production, profit, Rever business, data, contractor anticipated savings or for delay or for any financing costs or increase operating costs or any economic loss for any indirect or consequential loss or damage.

The report is purely based as stated, Pre purchase vehicle inspection, for all terms and Cond please visit our web page at expertinspectpro.com